



PRODUCT CHANGE NOTIFICATION (PCN) # 042417-001

IXYS COLORADO HAS FOUND IT NECESSARY TO IMPLEMENT A PRODUCT CHANGE. THIS NOTIFICATION IS TO INFORM YOU OF THE CHANGE WHICH MAY AFFECT YOUR PRODUCTS.

SUBJECT: IXRFD631 manufacturing directive and part number change to IXRFD631-NRF.		DOC NUMBER: PCN 042417-001
TYPE OF DOCUMENT: COMMERCIAL CUSTOMER NOTIFICATION – FOR POSTING TO IXYS COLORADO WEB SITE.		REVISION: N/A
<input type="checkbox"/> BILL OF MATERIAL <input checked="" type="checkbox"/> MANUFACTURING INSTRUCTION <input checked="" type="checkbox"/> DRAWING <input type="checkbox"/> OTHER		REVISION DATE: March 2017
DESCRIPTION OF CHANGE: The IXRFD631 is manufactured with material that is not rated for the high temperatures required for a reflow solder process. Therefore these devices are not recommended for use in manufacturing processes using solder reflow. As a part of this PCN, the product part number has been changed to IXRFD631-NFR from IXRFD631.		
REASON FOR CHANGE: <input type="checkbox"/> STANDARDIZATION <input type="checkbox"/> UPGRADE <input type="checkbox"/> PRODUCT SAFETY <input type="checkbox"/> MARKET DEMAND <input type="checkbox"/> CORRECTIVE ACTION <input type="checkbox"/> SAFETY <input checked="" type="checkbox"/> TECHNICAL REQUIREMENT <input type="checkbox"/> MANAGEMENT DECISION <input type="checkbox"/> OTHER **		
**Product discontinuation/consolidation		
REMARKS:		
PCN APPROVAL:		
PCN Initiator: Gilbert Bates Product Engineer		Date: April 25, 2017
Reviewed By: Steve Krausse General Manager		Date: April 25, 2017