



## PRODUCT CHANGE NOTIFICATION

**PCN No.:** 1042017-2

**Issue Date:** 10/4/2017

IXYS Colorado has found it necessary to change certain products. This notification is to inform you that this change may affect your products. If you have any comments on this notice please contact IXYS Colorado within 30 days of the PCN.

### REASONS FOR CHANGE:

Manufacturing is moving to laser engraving for device part numbering and any identifying marks that were previously inked for all IXYSRF devices.

### PCN TIME LINE:

Devices to be phased in by second quarter 2018

<b>IXYSRF Part No.:</b>	<b>Product Type:</b>	<b>Package Type:</b>	<b>Recommended Actions:</b>
DE475 all devices	MOSFET	DE475	None
DE375 all devices	MOSFET	DE375	None
DE275 all devices	MOSFET/Gate drivers	DE275	None
DE150 all devices	MOSFET	DE150	None
All TO-247 devices	MOSFET	TO-247	None
All TO-268 devices	MOSFET	TO-268	None
All SOT-227 devices	MOSFET	SOT-227	None
All ISOPLUS247 devices	MOSFET	ISOPLUS247	None

### PCN CREATED/UPDATED

DATE: 10/4/2017

ORIGINATOR: Gilbert Bates Product Engineer

REVIEWED BY: Steve Krausse General Manager